

E-10 Living

10.1 Living room Ceiling. Damaged, needs paint.



10.2 Living room entrance. Badly needs paint.



E-11 Toilet

11.1 Toilet window. 21 Mar 2021.

In addition to the common problem (unuseable; stuck shut), a new problem, after the tree outside was trimmed. The window leaks badly during the rain.



11.2 Toilet window. 21 Mar 2021.

Leaking badly, during rain.



E-12 Toilet

12.1 21 Mar 2021

Toilet window sill & cistern when raining. Window leaks badly during the rain.



12.2 Shower door. Badly needs repair.



E-13 Shower

13.1 Shower Window. Does not open. Badly needs repair & paint.



13.2 Shower Window. Badly needs repair and paint.



E-14 Bedroom 1

14.1 Bedroom 1 window 1. All windows are in a pathetic condition. No flyscreen.



14.2 Bedroom 1 window 2. Does not open. Cord broken.



E-15 Bedroom 3

15.1 Used for storage of WCH furniture (used; donations) that is not used.



15.2 Bedroom 3 carpet.



E-16 Doors

16.1 Bedroom 1 lock. I have access to this bedroom. The lock for the **unit** is "do not duplicate".



16.2 Bedroom 2 lock. I do not have access.



E-17 Sundry

17.1 Freezer is broken. Kept open to avoid smell.



17.2 Bedroom 1 curtains. Few windows have curtains. All curtains are home made, ill-fitting. Need proper curtains.

